



PMA Consultants

NAFS Photo Log 03.26.2021



Overview of east side



Overview of building from southwest side of site



Masonry construction along west side of building



Overview of interior southern apparatus bay




Masonry construction on western mezzanine



Southern apparatus bay exterior face



Overview of western mezzanine construction



Wiring and HVAC rough-ins in bunk area



Painted mechanical room



Western mezzanine steel beams




Interior framing at southern entrance



Mockup at job site trailer



Grouted geothermal wells



Ledger over gear room (03.23.2021)



Snow fence on admin side sloped roof.
Roofing installed (03.23.2021)



Roof hatch installed on admin side sloped
roof. Roofing installed (03.23.2021)