



Overview of building from southeast



Overview of building from northwest



Overview of building from northeast



Overview of building from southwest



GSI tank reinforcement delivery



GSI tank reinforcement install



Grouting the tile in the bathroom wall



Roof ladder installment



Installation of gutter on north side of the building



Gutter installation work on the other



Nichiha siding of the east side of building



Nichiha siding of the north side of building